



K7000
Series Cap Map

TIPS
 Got The Bends??
 Read This
 Do Not Hook Up Your Composite Sync To Both H & V On This Chassis
 Use H Only!!
 Leave V Empty
 Composite Sync
 Neg Comp Sync
 Pos Comp Sync
 C38 Value Determines Overall Width